


6076 Bumpstop Force vs. Displacement



NOTE: All TESTED BUSHINGS WERE WITHIN ± 5 OF THE GIVEN DUROMETER