


2 x 6077 Bumpstop Force vs. Displacement



NOTE: ALL TESTED BUSHINGS WERE WITHIN ± 5 OF THE GIVEN DUROMETER