


# 6075 Bumpstop Force vs. Displacement



NOTE: ALL TESTED BUSHINGS WERE WITHIN  $\pm 5$  OF THE GIVEN DUROMETER